



Safer Rig Services  
RSK  
Portview Road  
Avonmouth  
BS11 9JE

T: 01928 726 006  
E: Info@SaferRigServices.co.uk

# REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In Accordance with Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination	Date of Report	Customer Order	Site Colour	Report No.
15/04/2024	15/04/2024			2817056
Name & address of equipment owner		Examination Premises Address		
ADP Group Ltd Firing Close Farm Wooton - under - edge GL12 8PE		Comacchio GEO405 3092 (DR9)		

Specification of Equipment Examined	Serial No:	18-0189
TMA Hydraulic Winch	SWL:	367 Kg on layer 12 815Kg on layer 1
	Status:	No Defects Found
	Last Examined:	
	Manufacture Date:	
	Location	Comacchio GEO405 3092 (DR9)

First use after install?		Type of examination:
If YES, has the equipment been installed correctly?		Periodically scheduled inspection of 12 Months In accordance with an examination scheme
		<b>YES</b>

Any part found to have a defect which is or could become a danger to persons and a description defect:	
None	
Is the above a defect, which is of immediate danger to persons?	NO
Is the above a defect which is not yet but could become a danger to persons? (If YES state date by when)	NO
Particulars of any repair, renewal or alteration required to remedy the defect identified above:	
None	
Particulars of any tests carried out as part of the examination: (If none state NONE)	
None	
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>	
<b>YES</b>	

Details of any Defects / Repairs / Observations
None

Name and qualifications of Person making this report:	Name of person signing or authenticating this report on behalf of Safer Rig Services:	Latest Date by which next thorough examination must be carried out:
Matt Stokes  Inspector	Nick Reichelt  <i>Nick Reichelt</i> Signature:	<b>15/04/2025</b>

# REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In Accordance with Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination	Date of Report	Customer Order	Site Colour	Report No.
15/04/2024	15/04/2024			2817055
<b>Name &amp; address of equipment owner</b>			<b>Examination Premises Address</b>	
ADP Group Ltd Firing Close Farm Wooton - under - edge GL12 8PE			Comacchio GEO405 3092 (DR9)	

Specification of Equipment Examined	Serial No:	18-2306
TMA Hydraulic Winch	<b>SWL:</b>	1590 Kg on layer 4
	<b>Status:</b>	No Defects Found
	<b>Last Examined:</b>	
	<b>Manufacture Date:</b>	01/01/2018
	<b>Location</b>	Comacchio GEO405 3092 (DR9)

First use after install?		<b>Type of examination:</b>
If YES, has the equipment been installed correctly?		Periodically scheduled inspection of 12 Months In accordance with an examination scheme <span style="float: right; border: 1px solid black; padding: 2px;">YES</span>

<b>Any part found to have a defect which is or could become a danger to persons and a description defect:</b>	
None	
Is the above a defect, which is of immediate danger to persons?	NO
Is the above a defect which is not yet but could become a danger to persons? (If YES state date by when)	NO
<b>Particulars of any repair, renewal or alteration required to remedy the defect identified above:</b>	
None	
<b>Particulars of any tests carried out as part of the examination: (If none state NONE)</b>	
None	
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>	
<span style="background-color: green; color: white; padding: 5px; font-weight: bold;">YES</span>	

<b>Details of any Defects / Repairs / Observations</b>
None

<b>Name and qualifications of Person making this report:</b>  Matt Stokes  Inspector	<b>Name of person signing or authenticating this report on behalf of Safer Rig Services:</b>  Nick Reichelt  <div style="text-align: center;"><i>Nick Reichelt</i></div> Signature:	<b>Latest Date by which next thorough examination must be carried out:</b>  <div style="text-align: center; font-weight: bold;">15/04/2025</div>
--------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------



Safer Rig Services  
RSK  
Portview Road  
Avonmouth  
BS11 9JE

T: 01928 726 006  
E: Info@SaferRigServices.co.uk

# LOLER - THOROUGH INSPECTION OF ROTARY DRILL RIG

In Accordance with Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination	Date of Report	Customer Order	Site Colour	Report No.
15/04/2024	15/04/2024			2817051
<b>Name &amp; address of equipment owner</b>		<b>Examination Premises Address</b>		
ADP Group Ltd Firing Close Farm Wooton - under - edge GL12 8PE		Comacchio GEO405 3092 (DR9)		

Specification of Equipment Examined	Serial No:	Comacchio GEO405 3092 (DR9)
Rotary Rig	<b>SWL:</b>	6628 Kg
	<b>Status:</b>	No Defects Found
	<b>Last Examined:</b>	
	<b>Manufacture Date:</b>	
	<b>Location</b>	Comacchio GEO405 3092 (DR9)

First use after install?		<b>Type of examination:</b>
If YES, has the equipment been installed correctly?		Periodically scheduled inspection of 12 Months In accordance with an examination scheme
		<b>YES</b>

<b>Any part found to have a defect which is or could become a danger to persons and a description defect:</b>	
None	
Is the above a defect, which is of immediate danger to persons?	NO
Is the above a defect which is not yet but could become a danger to persons? (If YES state date by when)	NO
<b>Particulars of any repair, renewal or alteration required to remedy the defect identified above:</b>	
None	
<b>Particulars of any tests carried out as part of the examination: (If none state NONE)</b>	
None	
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>	
<b>YES</b>	

<b>Details of any Defects / Repairs / Observations</b>	
None	

<b>Name and qualifications of Person making this report:</b>  Matt Stokes  Inspector	<b>Name of person signing or authenticating this report on behalf of Safer Rig Services:</b>  Nick Reichelt  <i>Nick Reichelt</i>  Signature:	<b>Latest Date by which next thorough examination must be carried out:</b>  <b>15/04/2025</b>
--------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------

# LOLER - THOROUGH INSPECTION OF ROTARY DRILL RIG

In Accordance with Lifting Operations and Lifting Equipment Regulations 1998

CHECK	OK?	Comment
Track frame condition	OK	
Security of final drives	OK	
Security of track frame to main frame	OK	
Condition and security of turntable locking pin		
Check Turntable mounting bolts		
Check main frame for cracks	OK	
Condition of security of mast A frame	OK	
Condition and security of mast support	OK	
Check condition of mast raise cylinders	OK	
Check condition and security of mast cylinder pins	OK	
Check security of mast pins locking mechanism	OK	
Condition and security of front stabilisers	OK	
Condition and security of rear stabilisers	OK	
Check operation of front and rear stabilisers	OK	
Condition and security of operator console	OK	
Check all drill operations functions on console	OK	
Check for hydraulic leaks on console	OK	

CHECK	OK?	Comment
Condition and security of drill console controls	OK	
Check condition and availability of operation decals	OK	
Check all functions on drill set up controls	OK	
check for hydraulic leaks on set up controls	OK	
Condition and security of set up controls	OK	
Condition and security of fuel tank	OK	
Check fuel tank for leaks	OK	
Condition and security of hydraulic tank	OK	
Check hydraulic tank for leaks	OK	
Check operation and security of hydraulic oil cooler	OK	
Condition and security of inspection panels	OK	
Check security of engine and hydraulic pumps	OK	
Check condition and security of fan guards	OK	
Check condition of all pipe work inside engine bay	OK	Some leaves and debris inside inspection panel
Condition and security of batteries and cables	OK	
Condition and security of working platforms		
Condition and security of access ladders		

CHECK	OK?	Comment
Condition and security of flush pumps	OK	
Condition and security of flush pumps lines	OK	Some wear to hose
Condition and security of pressure lance and reeler	OK	
Check condition of hydraulic pipes on main frame	OK	
Check condition of electrical equipment	OK	
Check operation on all emergency stop buttons	OK	
Check condition and operation of CCTV		
Check condition and security of mast raise/lower mounting brackets	OK	
Check condition and security of mast raise/lower pins locking mechanism	OK	
Check condition and security of drill rotation cage	OK	
Check condition and security of drill rotation gate	OK	
Check operation of gate interlocking device	OK	
Check condition of interlocking electrical wiring	OK	
Check condition and security of rod holder		
Check condition and security of rod breaker	OK	

CHECK	OK?	Comment
Check condition and security of holder/breaker inserts	OK	
Check for hydraulic leaks on clamp cylinder	OK	
Check condition and security of casing extruder pulley		
Condition and security of casing extruder ropes		
Condition and security of head roller carriage	OK	
Condition and security of pulley and pins		
Check condition of carriage feed rope - chain	OK	
Check condition of carriage retract rope - chain	OK	
Check condition and security of carriage rollers	OK	
Check condition and security of carriage tilt cylinder		
Condition and security of rotation head	OK	
Condition and security of air/mud swivel	OK	
Condition and security of swivel locking mechanism	OK	
Check rotation head for oil leaks	OK	
check rotation head shock absorber	OK	
Check rotation head operation	OK	

CHECK	OK?	Comment
Condition and security of main feed/retract winch		
Check condition of handling winch rope	OK	
Check condition of wireline winch rope	OK	
Check condition of winch mounting brackets	OK	
Check condition and security of rope on drum	OK	
Check rope alignment on drum	OK	
Conditional and security of rope tension device	OK	
Check operation of main winch	OK	
Check condition and security of auxiliary winch	OK	
Check condition of winch mounting brackets	OK	
Check condition and security of winch rope	OK	
Check rope alignment on winch	OK	
Check condition of winch hook	OK	
Check operation of top end stroke sensor		
check operation and security of crown block	OK	
Check condition of crown block pulleys and pins	OK	
Check condition of hydraulic pipes on mast	OK	



CHECK	OK?	Comment
Check condition of electrical wiring on mast	OK	
Check for fire hazards eg clothing in engine bay	OK	
Fire extinguishers in place and last service in date		
Date last serviced	OK	30.11.23
Optional equipment fitted:		

<p><b>Name and qualifications of Person making this report:</b></p> <p><b>Matt Stokes</b></p> <p><b>Inspector</b></p>	<p><b>Name of person authenticating this report:</b></p> <p><b>Nick Reichelt</b></p> <p><i>Nick Reichelt</i></p> <p><b>Signature:</b></p>	<p><b>Latest Date by which next thorough examination must be carried out:</b></p> <p><b>15/04/2025</b></p>
-----------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------



Safer Rig Services  
RSK  
Portview Road  
Avonmouth  
BS11 9JE

T: 01928 726 006  
E: Info@SaferRigServices.co.uk

# REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In Accordance with Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination	Date of Report	Customer Order	Site Colour	Report No.
15/04/2024	15/04/2024			2817067
<b>Name &amp; address of equipment owner</b>		<b>Examination Premises Address</b>		
ADP Group Ltd Firing Close Farm Wooton - under - edge GL12 8PE		Comacchio GEO405 3092 (DR9)		

Specification of Equipment Examined	Serial No:	S0132111
6mm Wire Rope	SWL:	800 Kg
	Status:	No Defects Found
	Last Examined:	
	Manufacture Date:	
	Location	Comacchio GEO405 3092 (DR9)

First use after install?		<b>Type of examination:</b>
If YES, has the equipment been installed correctly?		Periodically scheduled inspection of 6 Months In accordance with an examination scheme <input type="checkbox"/> YES

<b>Any part found to have a defect which is or could become a danger to persons and a description defect:</b>	
None	
Is the above a defect, which is of immediate danger to persons?	NO
Is the above a defect which is not yet but could become a danger to persons? (If YES state date by when)	NO
<b>Particulars of any repair, renewal or alteration required to remedy the defect identified above:</b>	
None	
<b>Particulars of any tests carried out as part of the examination: (If none state NONE)</b>	
None	
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>	
<b>YES</b>	

<b>Details of any Defects / Repairs / Observations</b>	
None	

<b>Name and qualifications of Person making this report:</b>  Matt Stokes  Inspector	<b>Name of person signing or authenticating this report on behalf of Safer Rig Services:</b>  Nick Reichelt  <i>Nick Reichelt</i>  Signature:	<b>Latest Date by which next thorough examination must be carried out:</b>  <b>15/10/2024</b>
--------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------



Safer Rig Services  
RSK  
Portview Road  
Avonmouth  
BS11 9JE

T: 01928 726 006  
E: Info@SaferRigServices.co.uk

# REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In Accordance with Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination	Date of Report	Customer Order	Site Colour	Report No.
15/04/2024	15/04/2024			2817068
<b>Name &amp; address of equipment owner</b>		<b>Examination Premises Address</b>		
ADP Group Ltd Firing Close Farm Wooton - under - edge GL12 8PE		Comacchio GEO405 3092 (DR9)		

Specification of Equipment Examined	Serial No:	S021143 2
Wire Rope fitted with self locking swivel hook	<b>SWL:</b>	3233 Kg FOS 3:1 MBL 9700Kg
	<b>Status:</b>	No Defects Found
	<b>Last Examined:</b>	
	<b>Manufacture Date:</b>	
	<b>Location</b>	Comacchio GEO405 3092 (DR9)

First use after install?		<b>Type of examination:</b>
If YES, has the equipment been installed correctly?		Periodically scheduled inspection of 6 Months In accordance with an examination scheme
		<b>YES</b>

<b>Any part found to have a defect which is or could become a danger to persons and a description defect:</b>	
None	
Is the above a defect, which is of immediate danger to persons?	NO
Is the above a defect which is not yet but could become a danger to persons? (If YES state date by when)	NO
<b>Particulars of any repair, renewal or alteration required to remedy the defect identified above:</b>	
None	
<b>Particulars of any tests carried out as part of the examination: (If none state NONE)</b>	
None	
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>	
<b>YES</b>	

<b>Details of any Defects / Repairs / Observations</b>	
None	

<b>Name and qualifications of Person making this report:</b>  Matt Stokes  Inspector	<b>Name of person signing or authenticating this report on behalf of Safer Rig Services:</b>  Nick Reichelt  <i>Nick Reichelt</i>  Signature:	<b>Latest Date by which next thorough examination must be carried out:</b>  <b>15/10/2024</b>
--------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------