Rig Service & Maintenance Inspection			
Date:	21/07	7/2023	
	Comacchio GEO 601		
Make & Model:	4141		
Seriel Number:			-
Fleet reference number:	DR5		All work has been completed by competent, gualified
Hours:	4152		engineers, in line with manufacturers and DVSA
Next service due:	4402		recommendations and requirements.
Service Items	Checked	Changed	Comments
Ground level			
Condition of exterior hoses	√		
Emergency stops	√		
Guarding and safety interlocks	√		
ROM mode, operational	1		
Tracks/Running Gear			
Track tension and Condition	✓		
Track motor oil		✓	
Engine bay		-	
Engine oil & Filter		✓	
Air filters			
Fuel Filters		· ·	
Anti-freeze	✓	•	
	•	 ✓ 	
Hydraulic Filter	~	•	
Hydraulic Oil	*		Topped up.
Drill head/carriage			
Gear oil		✓	
Condition of all spiral binding	1		
Chain condition and tension		✓	Chain tension adjusted.
Chain wear	✓		
Mast slides	✓		
Head rollers/slides	✓		
Drill sample hammer	✓		
Winches			
Service winch & rope condition		✓	Service winch rope changed.
Service winch oil		✓	
Outside/external			
Control panel light/mast lighting	✓		
Grease points	✓	1	
Clamp faces		✓	Bottom clamp faces changed.
Beacon	1		
Mist pump oil	*	✓	
Additional Comments: Feed lever return spring changed. Pump pressure gauge fitted to body. Water swivel resealed.		ł	
Engine RPM switch on control panel cleaned. Filter added to fuel filler neck.			
Inspection completed by:	CW	Signature	b
Document signed off by:	TP	Signature	R

-

1

Г